

MONUMENT 238

Set post at $\frac{1}{4}$ section corner; Bur Oak 18 N2.5 W7.81, November 30, 1847.

This corner was fixed from subdivision stakes found along the E side of Rice St.; govt. witness trees gone; fixed corner tied it and set monument, June 01, 1896.