

MONUMENT 5

Intersect 3rd correction line 17.30 Chains W of corner to section 34, 35 TWP 31 R 23 set post corner to sections 4 & 5 Also 89.82 Chains N of SE corner of 5-30-23; Bur Oak 12 S10 W1.89, May 24, 1847.