

MONUMENT 234

Found boat spike at surface. Dug down 3.1 ft. and found nothing,
July 15, 1975.

Dug down 5.25 ft. and found granite monument in old bituminous road
surface, June 4, 1976.

Placed a 20 in. cast iron monument, June 23, 1976.

Monument removed for road construction by County. Replaced 20 in. cast
iron monument, no date given in field book.

Tied out monument, June 5, 1990.

Retied monument, December 1, 1998.

Tied out monument for construction, April 23, 2000.

Lowered monument and set 12 in. tube around monument, May 4, 2000.

Set a cast iron manhole assembly over monument, June 20, 2000.

Tied monument, July 31, 2007.